

Errata to the January 1, 2007, Georgia State Amendments to the International Mechanical Code, 2006 Edition

Update your copy of the January 1, 2007 Georgia Amendments to the 2006 International Mechanical Code by making the following corrections.

CHAPTER 4 VENTILATION

SECTION 405 SYSTEMS CONTROL

405.2 CO2 Sensors.

In the Amendment, change the word “shall” to “may”.

CHAPTER 6 DUCT SYSTEMS

SECTION 606 SMOKE DETECTION SYSTEMS CONTROL

606.2.1 Supply air systems.

In the Amendment, add second sentence to read:

Also, delete the end of the sentence from “in the return air duct or plenum upstream of any filters, exhaust air connections, outdoor air connections, or decontamination equipment and appliances.”

End of Errata.